

GLOUCESTER STREET

CDM 2015 Health & Safety Information

This information relates only to 'Significant Hazards' identified on this drawing and is to be read in conjunction with the Designer's Risk Assessment Register.

Demolition Plan Key

- Existing to be demolished
- Existing to be retained

Notes
All survey information based on surveys prepared by Clifton Surveys Ltd

| Rev | Date | Revision Details | Dr | Ch |
|-----|----------|--------------------|----|----|
| A | 15/10/24 | Revised annotation | AG | JW |



WESTWORKS
www.ecwestworks.com

Bristol: Westworks, Beacon Tower, Colston Street, Bristol, BS1 4XE
T 0117 214 1101 E bristol@ecwestworks.com

Sussex: 64 - 68 Brighton Road, Worthing, West Sussex, BN11 2EN
T 01903 248777 E sussex@ecarchitecture.com

London: 76 Great Suffolk Street, London SE1 0BL
T 020 7928 2773 E london@ecarchitecture.com

Client's Name
CROSSMAN GROUP

Job Title
CHRISTCHURCH HALL

Drawing Title
Level 01 Demolition Plan

Scale
10 0 10 20 30 40 50
Scale 1:1 @A2 mm



Drawn **AG** Checked **JW** Date **11/10/24**

| Job No | Origin | Vol | Level | Type | Role | Number | Status | Rev |
|--------|--------|-----|-------|------|------|--------|--------|-----|
| W0802 | WW | XX | B1 | DR | A | 1211 | S2 | A |

Status
PLANNING

CAD Plot Date: 15/10/2024 12:25:55

EXISTING STAIR TO BE RETAINED
SUBJECT TO DETAILED
CONDITION SURVEY

ACOUSTIC LINING FITTED BY BBC
TO BE REMOVED

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

INFILL WINDOW OPENINGS TO BE
DEMOLISHED AND WINDOWS
REINSTATED IN THIS LOCATION

NEW OPENING

EXISTING EXTERNAL OPENINGS
RETAINED

LOUVRED VENT TO BE REMOVED
AND REPLACED WITH GLAZING

EXISTING STAIR TO BE RETAINED
SUBJECT TO DETAILED
CONDITION SURVEY

PORTLAND STREET