

GLOUCESTER STREET

EXISTING STAIR TO BE RETAINED  
SUBJECT TO DETAILED  
CONDITION SURVEY

ACOUSTIC LINING & BOOTHS  
FITTED BY BBC TO BE REMOVED

NEW OPENING

EXISTING STAIR TO BE RETAINED  
SUBJECT TO DETAILED  
CONDITION SURVEY

PORTLAND STREET

**CDM 2015 Health & Safety Information**

This information relates only to 'Significant Hazards' identified on this drawing and is to be read in conjunction with the Designer's Risk Assessment Register.

**Demolition Plan Key**

- Existing to be demolished
- Existing to be retained

**Notes**

All survey information based on surveys prepared by Clifton Surveys Ltd

Rev	Date	Revision Details	Dr	Ch
A	15/10/24	Revised annotation	AG	JW




**Bristol:** Westworks, Beacon Tower, Colston Street, Bristol, BS1 4XE  
T 0117 214 1101 E bristol@ecwestworks.com  
**Sussex:** 64 - 68 Brighton Road, Worthing, West Sussex, BN11 2EN  
T 01903 248777 E sussex@eearchitecture.com  
**London:** 76 Great Suffolk Street, London SE1 0BL  
T 020 7928 2773 E london@eearchitecture.com

**WESTWORKS**  
www.ecwestworks.com

Client's Name  
**CROSSMAN GROUP**

Job Title  
**CHRISTCHURCH HALL**

Drawing Title  
**Level 02 Demolition Plan**



Drawn: **AG** Checked: **JW** Date: **11/10/24**

Job No	Origin	Vol	Level	Type	Role	Number	Status	Rev
W0802	WW	XX	B1	DR	A	1212	S2	A

Status  
**PLANNING**